

CAR / TRUCK > CAR / TRUCK - EQUIPMENT AND ACCESSORIES TO REPAIR TUBELESS



BEAD LEAK SEALER 8910

Code: MRI01SCXA0009

Safety Seal bead leak sealer. Eliminates all the leak caused by overused valve bead and rim deformation.







TOSI SNC



P.IVA 00875120503 www.tosisnc.net