

CAR / TRUCK > CAR / TRUCK - EQUIPMENT AND ACCESSORIES TO REPAIR TUBELESS



BEAD LEAK SEALER 8910

Code: **MRI01SCXA0009**

Safety Seal bead leak sealer.
Eliminates all the leak caused by overused valve bead and rim deformation.

TOSI SNC